



Navigation Warning

إنذار ملاحي

العوامة الملاحية لقناة دبي هاربر مفقودة

Dubai Harbour Approach Channel Navigational Buoy is Missing

We'd like to inform all the stations that Dubai Harbour Approach Channel Navigational Buoy **DHLP05** is reported missing from position.

Vessels in the area are advised to navigate with caution.

All VTS (Al Hamriyah port, Dubai Creek, Port Rashid, Fishing Harbours, Dubai Harbour and Jebel Ali Port) are requested to notify all vessels accordingly.

Owners, Agents, Charters, Marinas, Yacht Clubs, and Recreational Sailing Organizations shall ensure that the contents of this notice are made known to the masters or persons in charge of their vessels.

نود إبلاغ جميع المحطات أن العوامة الملاحية لقناة دبي هاربر **DHLP05** مفقودة من الموقع.

على كافة الوسائل البحرية العاملة في المنطقة الإبحار بحيطه وحذر.

على العاملين بنظام متابعة الوسائل البحرية في (ميناء الحمريه، وخور دبي وميناء راشد، ومرافئ الصيد وجبل علي) إخطار جميع السفن وفقاً لذلك.

على مالكي السفن والوكلاء والمستأجرين والمراسي ونوادي اليخوت والقوارب الترفيهية والشراعية الالتزام بإبلاغ قباطنة الوسائل البحرية أو الأشخاص المسؤولين على متنها بتطبيق محتويات هذا الإنذار.

Marine Operations Department
Dubai Maritime City Authority

إدارة العمليات البحرية
سلطة مدينة دبي الملاحية