

Regulation DD-44.0: Sign Board

44.1 Warning Signs

Lessees must provide warning signs in all potentially dangerous areas, such as chemical/ gas cylinder storage areas, machinery, drills etc. Lessees must provide safety signs for protective clothing as per working hazard, such as "WEAR SAFETY GEAR" for noisy areas, "WEAR MASK" for dusty operational areas, in addition to other signs like "NO SMOKING", FLAMMABLE STORAGE AREA" etc.